

MODEL	A cm	B cm	C cm	D cm	E cm	Rpm	Kg	potrebna moč
TSAP 3000	285	25	25	50	25	1000	1690	110-130
TSAP 3500	335	25	25	50	25	1000	1798	120-140
TSAP 4000	385	25	25	50	25	1000	1870	140-160

